State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

pal

Michael O. Leavitt Governor

Kathleen Clarke Executive Director Lowell P. Braxton Division Director 1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax)

801-538-7223 (TDD)

INSPECTION REPORT

Complete: X Exploration:

Inspection Date & Time: 3/15/00 8:30 to 9:30

Date of Last Inspection: 2/24/00
Mine Name: Gordon Creek Mines 2,7, & 8 County: Carbon Permit Number: ACT/007/016
Permittee and/or Operator's Name: Mountain Coal Company
Business Address: P. O. Box 591, Somerset, Colorado 81434
Type of Mining Activity: <u>Underground Mine</u>
State Officials(s): Susan White
Company Official(s): <u>Dan Guy</u> Federal Official(s): <u>None</u>
Weather Conditions: Fair and cold
Existing Acreage: Permitted-2286 Disturbed-20.3 Regraded Seeded Bonded
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded

Partial:__

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

Status: Active

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]		[X]	
2.	SIGNS AND MARKERS	[X]			\Box
3.	TOPSOIL	\Box	\Box	\Box	
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[X]	\Box	[X]	\Box
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[X]	\Box	[X]	\Box
c.	OTHER SEDIMENT CONTROL MEASURES	[X]	\Box	[X]	\Box
d.	WATER MONITORING	[X] [X]	\Box	[X]	\Box
e.	EFFLUENT LIMITATIONS	[X]	\Box	[X] [X] [X] [] []	
5.	EXPLOSIVES	\Box	\Box	\Box	\Box
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	\Box	\Box	\Box	\Box
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	\Box	\Box	\Box	
8.	NONCOAL WASTE	[X]		\Box	\Box
9.	PROTECTION OF FISH, WILDLIFE AND				
	RELATED ENVIRONMENTAL VALUES	\Box	\Box	· [_]	<u> </u>
10 .	SLIDES AND OTHER DAMAGE	\Box	\Box	\Box	Ц
11.	CONTEMPORANEOUS RECLAMATION			\Box	
12.	BACKFILLING AND GRADING		\Box		Ļ
13.	REVEGETATION		\Box		Ļ
14.	SUBSIDENCE CONTROL		\Box		Щ
15.	CESSATION OF OPERATIONS	\Box	\Box		\Box
16.	ROADS:				
a.		\Box	\Box		Ļļ
	DRAINAGE CONTROLS	\Box	\Box		ĻĻ
17.	OTHER TRANSPORTATION FACILITIES		\Box	Щ	لِـلِ
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS			Ц	Щ
19.	AVS CHECK (4th Quarter-April, May, June)(date)	\Box		Ц	Ц
20.	AIR QUALITY PERMIT		Ц	\coprod	$\coprod_{z \in A}$
21.	BONDING & INSURANCE	[X]	Ш	[X]	

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: ACT/007/016

DATE OF INSPECTION: 3/15/00

(Comments are Numbered to Correspond with Topics Listed Above)

Consumers Road to the site had been plowed only to the Horizon Mine, the road was not passable to the Gordon Creek Mine site.

1. Permits, Change, Transfer, Renewal, Sale

UPDES permit #UTG04004 has one discharge point, 001A. The permit expires April 30, 2001.

The permit was renewed August 28, 1999. One condition was attached to the permit as follow:

"Mountain Coal Company, LLC will submit water quality data electronically to the Division for the Gordon Creek #2, #7 and #8 Mine beginning with data for the fourth quarter of 1999."

Ken Wyatt, Division Hydrologist, stated that data had been submitted electronically, however all the data appeared as zeros. The Division is continuing to work with the Operator in electronic submission of data. This issue was discussed with Mary Ann Wright, Associate Director, and concluded that no NOV's will be issued.

4. Hydrologic Balance:

- **b. Sediment Ponds and Impoundments:** Fourth quarter pond inspection was completed by Dan Guy on October 19, 1999. 2/7/8 Sediment Pond, Jacobs Pond, and Sweets Pond were included in the inspection.
- c. Other Sediment Control Measures: Straw bales will be placed within the disturbed area to treat runoff from the Fan Portal area. The Operator should install the bales as soon as possible.
- d. Water Monitoring: Water monitoring was not viewed. The Operator has been submitting hard copies of data to the Division. The Division told Operators if they submit electronically then they don't have to provide hard copies. Water data will be viewed next inspection.
- **e. Effluent Limitations**: Only December's DMR was found at the SLC office. The Operator's files will be viewed next inspection.
- **21. Bonding and Insurance:** Liberty Mutual Insurance Company holds the \$641,443.00 bond. St. Paul Fire & Marine Insurance Company carries a \$500,000 general liability coverage which expires 7/31/00.

Copy of this Report:	
Mailed to: OSM, Chris Hansen (CFC), Dan Guy (Blackhawk Engineering)	
Given to: Pamela Grubaugh-Littig (DOGM)	
•	

Inspector's Signature: New M. White #35

sm

 $O: \label{local_compliance} O: \label{local_compliance}$